

Closed Work Orders for Marina Green Marinas – July 1, 2007 through Oct. 3, 2007

SM-28940	1346-WMARINA	10/01/2007		09/28/2007
<b>Action:</b> Main dock near Gate 33: 1) main dock separating (carpenters have done repairs); 2) water hose leak (plumber has made repairs). Thanks! Priority: Medium				
SM-28951	1346-WMARINA	10/01/2007		09/28/2007
<b>Action:</b> Gate 31, pump out dock: Please install dock ladder (work done by onsite carpenters). SpecialComment: contact: larry Priority: Medium				
SM-28366	1346-WMARINA	09/13/2007	09/14/2007	09/19/2007
<b>Action:</b> Gate 11, slip 107: tenant reports that electrical breaker is faulty. (Discussed with Dominick in RPD Electrical Dept.) SpecialComment: contact: office or Larry Priority: Medium				
SM-28180	1346-WMARINA	09/10/2007	09/10/2007	09/13/2007
<b>Action:</b> Gate 11, slip 105: tenant reports that breaker is tripping repeatedly. (She reports that this began last Friday, 9/7/07. SpecialComment: contact: larry Priority: Medium				
SM-27947	1346-EMARINA	08/31/2007		08/31/2007
<b>Action:</b> Gate 14: Gate frame loose. Onsite carpenters are working on repair now. thanx. SpecialComment: contact: larry Priority: Medium				
SM-27958	1346-EMARINA	08/31/2007		09/10/2007
<b>Action:</b> Gate 6, near slip 242 at water hatch: small, pinhole leak in water line. (Not major, but should be addressed.) SpecialComment: contact: brad or larry Priority: Medium				
SM-27359	1346-WMARINA	08/14/2007		08/29/2007
<b>Action:</b> Gate 31: As discussed with onsite carpenters, minor deck board repairs near slip 567, and water hatch repair. SpecialComment: contact: larry Priority: Medium				
SM-27038	1346-WMARINA	08/03/2007		08/02/2007
<b>Action:</b> REPLACE CAP ON VACUME CORD.				
SM-26801	1346-EMARINA	07/27/2007	07/27/2007	07/27/2007
<b>Action:</b> Gate 10, near slip 380: Elect. outlet has apparent short, staff noticed tingling sensation, witnessed spark when plugging in cord; also loud pop. Top outlet is brown/black. (Electrician supv. notified by phone.) SpecialComment: contact: larry Priority: Medium				
SM-26749	1346-WMARINA	07/25/2007		08/03/2007
<b>Action:</b> Gates 3 and 5 are difficult to open. Marina staff suggest that iron shop assess, make repairs as needed. SpecialComment: contact: larry Priority: Medium				
SM-26649	1346-EMARINA	07/23/2007		07/30/2007
<b>Action:</b> As discussed with onsite carpenters: Gate 4--cleats needed on ramp; Gate 14--cleats needed on ramp. SpecialComment: contact: larry Priority: Medium				
SM-26650	1346-EMARINA	07/23/2007		07/24/2007
<b>Action:</b> Gate 4: graffiti on north side of gangway. SpecialComment: contact: larry Priority: Medium				
SM-26653	1346-WMARINA	07/23/2007		08/14/2007
<b>Action:</b> As discussed with onsite carpenters: Cleats needed on ramps at Gates 7, 9, 15, 17, 21, 23, and 27. Also: Gate 21: rotten deck board near slip 157; Gate 23, broken water hatch near slip 177, tension rod sticking out near slip 205 (street side of dock), loose boards near slip 211; Gate 27: water hatches at slips 261 and 281; rotten deck boards near 273 and 281. SpecialComment: contact: larry Priority: Medium				

SM-26589	1346-WMARINA	07/20/2007		07/26/2007
<b>Action:</b> As discussed with onsite carpenters, minor deckboard repairs at: Gate 3: (near 39/41) Gate 5: (between 35 & 57) Gate 7: (between 36-83) <b>SpecialComment:</b> contact: larry <b>Priority:</b> Medium				
SM-26471	1346-WMARINA	07/17/2007		07/23/2007
<b>Action:</b> Gate 29, as discussed with onsite carpenters, water hatches need repair at the following areas: slips 289/291; 317/319, 321/323, 357/359. <b>SpecialComment:</b> contact: larry <b>Priority:</b> Medium				
SM-26472	1346-EMARINA	07/17/2007		07/18/2007
<b>Action:</b> Gate 10, near slip 364: as discussed with onsite carpenters, main dock needs repair. <b>SpecialComment:</b> contact: larry <b>Priority:</b> Medium				
SM-26429	1346-WMARINA	07/16/2007		07/18/2007
<b>Action:</b> Gate 29, between slip 301 and 303: Spigot handle has broken. Replacement requested by harbor tenant. <b>SpecialComment:</b> contact: larry <b>Priority:</b> Medium				
SM-26255	1346-EMARINA	07/10/2007		07/11/2007
<b>Action:</b> Gate 2, near slip 58: tension rods are loose (work done by onsite carpenters). <b>Priority:</b> Medium				
SM-26173	1346-EMARINA	07/06/2007	07/23/2007	07/25/2007
<b>Action:</b> Gate 14: several dock lights near gate are on during daytime. <b>SpecialComment:</b> contact: larry <b>Priority:</b> Medium				
SM-26178	1346-EMARINA	07/06/2007		07/10/2007
<b>Action:</b> Gate 2, near slip 68: dock/finger separating; carpenters onsite now (thank you) <b>Priority:</b> Medium				
SM-25950	1346-EMARINA	06/28/2007		07/19/2007
<b>Action:</b> Gate 10, near slip 380, main dock: needs repair as discussed with onsite carpenters. <b>SpecialComment:</b> contact: larry <b>Priority:</b> Medium				
SM-24449	1346-WMARINA	05/10/2007		07/20/2007
<b>Action:</b> Please paint newly repaired electrical box at top of Gate #33.				
SM-21331	1346-EMARINA	01/30/2007		07/26/2007
<b>Action:</b> Gate 16, slip 638: Whaler (boat side, near corner) is split; also, main dock is bowing out (north side), should be inspected. <b>SpecialComment:</b> contact: larry <b>Priority:</b> Medium				
SM-21333	1346-EMARINA	01/30/2007		07/26/2007
<b>Action:</b> Gate 16, slip 640/642, (west of fire box, north side of main dock): bolts loose, main dock loose. <b>SpecialComment:</b> contact: larry <b>Priority:</b> Medium				
SM-21334	1346-EMARINA	01/30/2007		07/26/2007
<b>Action:</b> Gate 16, near slip 626: Tension rod coming out (north side of dock). <b>SpecialComment:</b> contact: larry <b>Priority:</b> Medium				
SM-21337	1346-EMARINA	01/30/2007		07/26/2007
<b>Action:</b> Gate 16, slip 650: Main dock deck board has hole (south side of dock). <b>SpecialComment:</b> contact: larry <b>Priority:</b> Low				
SM-21338	1346-EMARINA	01/30/2007		07/26/2007
<b>Action:</b> Gate 16, slip 632: main dock deck board has hole. <b>SpecialComment:</b> contact: larry <b>Priority:</b> Low				
SM-21339	1346-EMARINA	01/30/2007		07/26/2007
<b>Action:</b> Gate 16, slip 606: Main dock deck board has hole. <b>SpecialComment:</b> contact: larry <b>Priority:</b> Low				

SM-20620	1346-WMARINA	01/08/2007	07/26/2007
<b>Action:</b> Gate 27 ramp: deck cleats needed on ramp near bottom. (One missing, one broken) SpecialComment: contact: larry Priority: Medium			
SM-20571	1346-EMARINA	01/05/2007	07/26/2007
<b>Action:</b> Gate 6, slip 244: main dock bolts are loose. SpecialComment: contact: larry Priority: Medium			
SM-20572	1346-EMARINA	01/05/2007	07/26/2007
<b>Action:</b> Gate 6, slip 214: bolts loose SpecialComment: contact: larry Priority: Medium			
SM-20425	1346-EMARINA	01/02/2007	07/26/2007
<b>Action:</b> Gate 4, slip 98: TRIP HAZARD - main dock is separating, lifting deck boards. On site carpenters notified. SpecialComment: Related W.O.: SM-15124 Priority: Medium			
SM-20337	1346-EMARINA	12/27/2006	07/26/2007
<b>Action:</b> Gate 31: approx. 20 feet north of ramp, dock is loose across whole of dock. Temporary repairs made per on-site carpenters instructions to marina staff. SpecialComment: contact: larry Priority: Medium			
SM-19096	1346-EMARINA	11/14/2006	07/26/2007
<b>Action:</b> Gate 4, slip 90/92: Main dock near hinges appears to be separating, per marina staff. SpecialComment: contact larry Priority: Medium			
SM-19007	1346-WMARINA	11/09/2006	07/26/2007
<b>Action:</b> Gate 31, near slip 575: Per onsite carpenters working on structural, plumbing is deteriorating, needs replacement. Plumbers should contact onsite carpenters. SpecialComment: contact larry Priority: Medium			
SM-19016	1346-WMARINA	11/09/2006	07/26/2007
<b>Action:</b> Gate 15 ramp and main dock: 1) beam for rollers acting as wheels at bottom of ramp has separated from bottom of ramp; 2) bottom of ramp beams sliding on wood. 3) Main dock at bottom of ramp appears to have structural separation. Ramp too heavy for workboat hoist, truck hoist will be needed. SpecialComment: contact larry Priority: Medium			
SM-19017	1346-WMARINA	11/09/2006	07/26/2007
<b>Action:</b> Gate 15, slip 137: rot at finger end per carpenter/marina staff SpecialComment: contact larry Priority: Medium			
SM-18219	1346-WMARINA	10/19/2006	07/26/2007
<b>Action:</b> Gate 33, slip 689: whaler at end of finger fallen off, needs replacement. (Finger end w/fender wheel & bracket is in my office) SpecialComment: contact larry Priority: Medium			
SM-17680	1346-EMARINA	10/02/2006	07/26/2007
<b>Action:</b> code 010 gate 16, slips 656-658: finger is working loose from header per marina staff SpecialComment: contact: larry Priority: Medium			
SM-16527	1346-EMARINA	08/23/2006	07/26/2007
<b>Action:</b> Gate 8, slip 300-302 End Tie on outside: whaler is split SpecialComment: cx: larry Priority: Medium			
SM-16141	1346-EMARINA	08/09/2006	07/26/2007
<b>Action:</b> Gate 8, slip 264: Main dock header cracked. SpecialComment: contact: larry Priority: Medium			
SM-15841	1346-EMARINA	08/02/2006	07/26/2007
<b>Action:</b> Gate 2, End tie fingers (slips 38 and 40): Boards are loose, foam may be needed. SpecialComment: Contact: Larry Priority: Medium			
SM-15874	1346-EMARINA	08/02/2006	07/26/2007
<b>Action:</b> Gate 2, Slip 78: Foam may be needed. SpecialComment: Contact: Larry Priority: Medium			

SM-15875	1346-EMARINA	08/02/2006	07/26/2007
<a href="#">Action:</a> Gate 2, Slip 80: Boards bad, may need foam. <a href="#">SpecialComment:</a> Contact: Larry Priority: Medium			
SM-15876	1346-EMARINA	08/02/2006	07/26/2007
<a href="#">Action:</a> Gate 4, Slip 84: foam needs adjustment. <a href="#">SpecialComment:</a> Contact: Larry Priority: Medium			
SM-15877	1346-EMARINA	08/02/2006	07/26/2007
<a href="#">Action:</a> Gate 4, Slip 86: Finger loose from main dock, floatation. <a href="#">SpecialComment:</a> Contact: Larry Priority: Medium			
SM-15878	1346-EMARINA	08/02/2006	07/26/2007
<a href="#">Action:</a> Gate 4, Slip 112: Deckboard has hole; main dock header bad, floatation needed. <a href="#">SpecialComment:</a> Contact: Larry Priority: Medium			
SM-15879	1346-EMARINA	08/02/2006	07/26/2007
<a href="#">Action:</a> Gate 4, Slip 116: Header at finger end is missing; floatation needed; cross header to main dock split. <a href="#">SpecialComment:</a> Contact: Larry Priority: Medium			
SM-15881	1346-EMARINA	08/02/2006	07/26/2007
<a href="#">Action:</a> Gate 4, Slip 122: Whaler bad <a href="#">SpecialComment:</a> Contact: Larry Priority: Medium			
SM-15883	1346-EMARINA	08/02/2006	07/26/2007
<a href="#">Action:</a> Gate 4, Slip 132: Finger may need floatation. <a href="#">SpecialComment:</a> Contact: Larry Priority: Medium			
SM-15884	1346-EMARINA	08/02/2006	07/26/2007
<a href="#">Action:</a> Gate 4, slip 134: Hole in deck board. <a href="#">SpecialComment:</a> Contact: Larry Priority: Medium			
SM-15885	1346-EMARINA	08/02/2006	07/26/2007
<a href="#">Action:</a> Gate 4, slip 136: finger may need floatation, bracing. <a href="#">SpecialComment:</a> Contact: Larry Priority: Medium			
SM-15886	1346-EMARINA	08/02/2006	07/26/2007
<a href="#">Action:</a> Gate 4, slip 138: finger bad at end, deck boards need replacing, temporary plywood and cones placed by marina staff. <a href="#">SpecialComment:</a> Contact: Larry Priority: Medium			
SM-15887	1346-EMARINA	08/02/2006	07/26/2007
<a href="#">Action:</a> Gate 4, slip 140: foam missing <a href="#">SpecialComment:</a> Contact: Larry Priority: Medium			
SM-15888	1346-EMARINA	08/02/2006	07/26/2007
<a href="#">Action:</a> Gate 4, slip 146: end header bad, deckboard needs replacement. <a href="#">SpecialComment:</a> Contact: Larry Priority: Medium			
SM-15889	1346-EMARINA	08/02/2006	07/26/2007
<a href="#">Action:</a> Gate 4, slip 148: header missing on finger. <a href="#">SpecialComment:</a> Contact: Larry Priority: Medium			
SM-15891	1346-EMARINA	08/02/2006	07/26/2007
<a href="#">Action:</a> Gate 4, slip 160: finger needs foam. <a href="#">SpecialComment:</a> Contact: Larry Priority: Medium			
SM-15893	1346-EMARINA	08/02/2006	07/26/2007
<a href="#">Action:</a> Gate 4, slip 168: finger has deck rot. <a href="#">SpecialComment:</a> Contact: Larry Priority: Medium			
SM-15288	1346-EMARINA	07/17/2006	07/26/2007
<a href="#">Action:</a> Gate 2, Slip 66: whaler has some rot, uneven deck boards <a href="#">SpecialComment:</a> contact: larry Priority: Medium			
SM-15289	1346-EMARINA	07/17/2006	07/10/2007
<a href="#">Action:</a> Gate 2, slip 68: main deck board warped <a href="#">SpecialComment:</a> contact: larry Priority: Medium			

SM-15294	1346-EMARINA	07/17/2006	07/26/2007
<b>Action:</b> Gate 2, slip 74: nails sticking up--hazard. SpecialComment: contact: larry Priority: Medium			
SM-15209	1346-EMARINA	07/14/2006	07/26/2007
<b>Action:</b> Gate 2, Slip 12: Angle iron brackets, carriage bolts need replacement. SpecialComment: Contact: Larry Priority: Medium			
SM-15212	1346-EMARINA	07/14/2006	07/26/2007
<b>Action:</b> Gate 2: main dock header has split SpecialComment: Contact: Larry Priority: Medium			
SM-15213	1346-EMARINA	07/14/2006	07/26/2007
<b>Action:</b> Gate 2, Slip 26: Near Elect panel, main dock board loose. SpecialComment: Contact: Larry Priority: Medium			
SM-15215	1346-EMARINA	07/14/2006	07/26/2007
<b>Action:</b> Gate 2, Slip 28: broken board, main dock header loose, may need foam also. SpecialComment: Contact: Larry Priority: Medium			
SM-15218	1346-EMARINA	07/14/2006	07/26/2007
<b>Action:</b> Gate 2, Slip 34: Hld in deck board in finger, whaler rotten, finger end header loose, needs foam. SpecialComment: Contact: Larry Priority: Medium			
SM-15220	1346-EMARINA	07/14/2006	07/26/2007
<b>Action:</b> Gate 2, slip 58: main dock has hole and rot, main dock deck board warped, loose. SpecialComment: contact: Larry Priority: Medium			
SM-15221	1346-EMARINA	07/14/2006	07/26/2007
<b>Action:</b> Gate 2, slip 52: foam needed at end of finger, carriage bolts loos SpecialComment: Contact: Larry Priority: Medium			
SM-15222	1346-EMARINA	07/14/2006	07/26/2007
<b>Action:</b> Gate 2, slip 48: foam needed on finger SpecialComment: Contact: Larry Priority: Medium			
SM-15225	1346-EMARINA	07/14/2006	07/26/2007
<b>Action:</b> Gate 2, slip 38: Pile collar bolts loose. SpecialComment: Contact: Larry Priority: Medium			
SM-15126	1346-EMARINA	07/12/2006	07/26/2007
<b>Action:</b> Gate 8, Slip 312: Finger needs two full foam billets installed. SpecialComment: Contact: Larry Priority: Medium			
SM-15136	1346-WMARINA	07/12/2006	07/26/2007
<b>Action:</b> Gate 33, Slip 691: Finger missing foam (staff reports 2 billets needed). SpecialComment: Contact: Larry Priority: Medium			
SM-15137	1346-WMARINA	07/12/2006	07/26/2007
<b>Action:</b> Gate 33, Slip 695: Foam is not secure, coming out from under end of finger. SpecialComment: Contact: Larry Priority: Medium			

Closed Work Orders for Harbormasters Office -- July 1, 2007 through Oct. 3, 2007

SM-28682	1690-BLDG	09/24/2007	09/24/2007
<b>Action:</b> Vehicle transport: (Actual location at Marina workshop). Please pick up Toro cart 651- V-190, transport to			

Auto Shop; return when repairs made. (Please pick up electric cart at Auto shop first--existing work order number is SM-27476 to transport to marina). SpecialComment: contact: larry Priority: Medium

SM-27815	1690-BLDG	08/28/2007	08/29/2007
----------	-----------	------------	------------

Action: Install valves to hot and cold lines to showers as discussed with Plumbing Supv. SpecialComment: contact: larry Priority: Medium

SM-27476	1690-BLDG	08/17/2007	08/21/2007
----------	-----------	------------	------------

Action: Transport elect. cart 651 E 121 from marina work shop to RPD auto shop, and return when repairs are made. Please call Larry at 218-1053 before pickup, thanks. SpecialComment: Please contact larry at 218-1053 Priority: Medium

SM-27397	1690-FEMALE	08/15/2007	08/22/2007
----------	-------------	------------	------------

Action: Light in alcove (actually outside restroom) is out. SpecialComment: contact: larry Priority: Medium

SM-27398	1690-BLDG	08/15/2007	08/21/2007
----------	-----------	------------	------------

Action: Office interior light bulb is out in cupola. SpecialComment: contact: larry Priority: Medium

SM-26547	1690-BLDG	07/19/2007	07/20/2007
----------	-----------	------------	------------

Action: PLEASE DELIVER SUPPLIES FROM STOREROOM TO S.F. MARINA OFFICE. Priority: Medium

SM-25568	1690-MALE	06/19/2007	07/02/2007
----------	-----------	------------	------------

Action: As discussed with sheetmetal worker Dave, repair sharp edge on toilet stall door/partition. Priority: Medium

Closed Work Orders for Marina Green Hardscaped Areas -- July 1, 2007 through Oct. 3, 2007

---

SM-28349	MARIGNHS-SIDEWALK	09/13/2007	09/17/2007
----------	-------------------	------------	------------

Action: Safety Hazards: Near Webster St. entrance at Par Course/work out area: 1) post for work out bar is unstable--please remove; 2) metal bar sticking up from ground, needs removal or cut back; 3) handles on work out post are loose. SpecialComment: contact: larry Priority: Medium

SM-28211	MARIGNHS-PATH	09/10/2007	09/10/2007
----------	---------------	------------	------------

Action: Stencil on paths at greens "KEEP CLEAR" 4 sets.

---

Closed Work Orders for Marina Green Parking Lots -- July 1, 2007 through Oct. 3, 2007

---

SM-28576	1398-W-PRK	09/20/2007	09/21/2007
----------	------------	------------	------------

Action: Please paint over all the concrete road dividers that are covered with graffiti. You will most likely need to come and spray them all because of the size and amount. The color is white. About one dozen dividers. Thank you, Joseph.

SM-28305	1398-MARINA- P	09/12/2007	09/17/2007
----------	----------------	------------	------------

Action: Disabled Parking sign knocked over/broken at ground level. Pole w/sign removed, stored in workshop. SpecialComment: contact: larry Priority: Medium

SM-28313	1398-W-PRK	09/12/2007	09/18/2007
----------	------------	------------	------------

Action: Two Disabled Parking signs knocked over/broken at base. Poles w/signs in workshop. One location at handicapped parking on Yacht Rd. by West Restrooms (marked by cone); other sign on north side of Little Marina Green near walkway. SpecialComment: contact: larry Priority: Medium

---

SM-27881	1398-W-PRK	08/30/2007	09/06/2007
<b>Action:</b> Please align K-rails along curb (or remove if possible)no later that Sept. 7. K- rails are located in parking lot on east side of St. Francis YC. Thanks SpecialComment: contact: larry Priority: Medium			
SM-27436	1398-MARINA- P	08/15/2007	08/28/2007 08/29/2007
<b>Action:</b> Light Standard Pole Number 39 light is out (near Gate 33). SpecialComment: contact: larry Priority: Medium			
SM-27210	1398-W-PRK	08/09/2007	09/19/2007
<b>Action:</b> Safety issue: Stop sign pole on Yacht Rd near s/w corner of Little Marina Green, inside RPD property, has been knocked down. Temporary stop sign placed on barricade by marina staff. SpecialComment: Safety issue; contact: Larry Priority: Medium			
SM-26958	1398-W-PRK	08/02/2007	08/08/2007
<b>Action:</b> Safety Issue. Near Gate 23: hole in asphalt sidewalk (approximately size of softball) on trench patch. No apparent support visible under trench patch. Cone and barricade placed by marina staff. SpecialComment: Contact: Larry Priority: Medium			
SM-26607	1398-W-PRK	07/20/2007	07/24/2007
<b>Action:</b> Please paint over grafitti on road barriers that have been placed in the parking lot near the waters edge. Thank you, Joseph.			
SM-26072	1398-E-PRK	07/03/2007	07/12/2007
<b>Action:</b> Please core drill 4 holes around garbage bin at gate 10, Holes are marked. Notify iron shop after work is done.			
SM-26059	1398-E-PRK	07/02/2007	07/19/2007
<b>Action:</b> Debris box near Gate 10: please install chain link fence as discussed with iron shop and cement shop. SpecialComment: contact: larryh Priority: Medium			
SM-24597	1398-W-PRK	05/16/2007	09/04/2007
<b>Action:</b> At Handicap Parking space near Harbor Office: paint existing Handicap space with cross hatch, make adjacent parking space (to south)into Handicap space. Paint blue on raised wall in front of new space, place pole for sign in front new handicap parking space (use sign from existing pole), and place "No Parking" sign on existing pole in front of new crosshatch area. SpecialComment: contact: Larry or Brad Priority: Medium			
SM-23771	1398-E-PRK	04/17/2007	07/09/2007
<b>Action:</b> Debris boxes at Gates 10 and 16 need enclosures; chain-link fence with slats, gated in front to allow pick up by sanitation trucks (discussed with Iron Shop) SpecialComment: Contact: larry Priority: Medium			
SM-17621	1398-E-PRK	10/02/2006	09/05/2007
<b>Action:</b> Paint Shop: Please repaint dividing line and crosswalk by par course entrance to Marina Green on Marina Blvd. near Webster St. Area was repaved and drivers need some guidelines! Thanks.			